



Ecoflores  
ul. Waksmundzka 34  
34-400 Nowy Targ  
Poland  
www.ecoflores.eu  
kontakt@ecoflores.eu  
T: +48-604-508-229

## Certificate of Analysis

Date 05.08.24  
Page 1 / 1

### Product

**CANDLE DYE - LILAC**

Batch 75889

Analysis: 70669 Inspection criterion	Test	Specification		Result
		min	max	
Delta E CMC (1:1)	TA - 9.1 - 001		1,000	0,370
Delta L	TA - 9.1 - 001		report only	0,240
Delta a	TA - 9.1 - 001		report only	-0,060
Delta b	TA - 9.1 - 001		report only	-0,420
optical assessment	TA - 9.1 - 045		report only	Pass

The analytical results above refer to the given batch. The analysis which were carried out certify the conformity with the product specifications, but they do not guarantee the applicability for every application.

The certificate of Analysis does not release the downstream user of the product from its liability for incoming goods inspection.

This certificate has been electronically generated and is therefore not signed.