



Ecoflores
ul. Waksmundzka 34
34-400 Nowy Targ
Poland
www.ecoflores.eu
kontakt@ecoflores.eu
T: +48-604-508-229

Certificate of Analysis

Date 05.08.24
Page 1 / 1

Product

CANDLE DYE - PURPLE

Batch

77022 SG

Analysis: 72268 Inspection criterion	Test	Specification		Result
		min	max	
Delta E CMC (1:1)	TA - 9.1 - 001		1,000	0,480
Delta L	TA - 9.1 - 001		report only	0,030
Delta a	TA - 9.1 - 001		report only	0,380
Delta b	TA - 9.1 - 001		report only	0,500
optical assessment	TA - 9.1 - 045		report only	Pass

The analytical results above refer to the given batch. The analysis which were carried out certify the conformity with the product specifications, but they do not guarantee the applicability for every application.

The certificate of Analysis does not release the downstream user of the product from its liability for incoming goods inspection.

This certificate has been electronically generated and is therefore not signed.